INSTALLATION GUIDE - WM2245

L

N

Connect N indicator to black or white wire

Connect L indicator to black or white wire

E

1. **Drill the mounting bracket and cable gripper nut into the ceiling with screws and anchors.**

2. **Use the wire connector to connect the driver to the supply wires according to labels on the wires.**

3. **Align holes of the canopy with the mounting bracket and secure the canopy with screws.**

4. **Push the cable gripper to pass the cable through it, and screw the cable gripper up into the nut.**