


Installation Process:

1. Drill the mounting bracket into the wall with screws and even anchors (these come with the light).
2. Use the wire connector to connect the wires of the light to the supply wires according to labels on the wires.
3. Align the canopy holes with the mounting bracket and secure the canopy with bolts and dome cap nuts.
4. Put each series of crystal on the canopy.



WM1078-520

WM1078-680


A	Lap 1:14# octagonal beads *2+40# crystal balls	6 series
B	Lap 2:14# octagonal beads *3+40# crystal balls	1 series

WM1078-800


A	Lap 1:14# octagonal beads *2+40# crystal balls	8 series
B	Lap 2:14# octagonal beads *3+40# crystal balls	6 series
C	Lap 3:14# octagonal beads *4+40# crystal balls	1 series

WM1078-1000

A	Lap 1:14# octagonal beads *2+40# crystal balls	10 series
B	Lap 2:14# octagonal beads *3+40# crystal balls	12 series
C	Lap 3:14# octagonal beads *4+40# crystal balls	6 series
D	Lap 4:14# octagonal beads *5+40# crystal balls	1 series



A flimsy ceiling



An open area



High temperature and humidity